Vegetation blocking a sight triangle at a Johns Creek junction is a genuine safety issue and sometimes a code matter. Pruning to restore visibility is straightforward and prevents collisions. Document the *Find more information* before and after. Sight line notes at %LINK%.